



# YELLOW ALERT!

## ***DOSH/OSHA Recordable***

**Date:** January 2011

**Re:** OSHA Recordable

The following DOSH/OSHA Recordable has occurred. In an effort to prevent similar injuries from occurring at your location, please review the injury summary shown below. Remember that a Supervisor's Incident Report is to be completed and faxed to ERNWest, within 24 hours of notification of the incident. Every accident/incident will be investigated regardless of the extent of injuries. Even a near miss or minor injury can give you causes that may stop a more serious accident from occurring in the future. Your experienced based recommendations and ideas for prevention of such an accident are welcomed and **needed**.

**I. Injury Summary:**

<b>Date Of Injury:</b>	December 9, 2010
<b>Date Reported:</b>	December 9, 2010
<b>Injury Type:</b>	Electrocution
<b>Injury Cause:</b>	Employee was removing coat from coat rack. A metal hanger swung down and entered outlet shocking employee. Employee was OK and did not miss any work.
<b>Action Taken to Prevent Reoccurrence:</b>	The accident investigation revealed the coat rack was too close to outlet and was moved to a new location.  This is one of those unforeseen conditions that could have resulted in much greater injury or death.